

ADDITIONAL PHOTOS FOR  
SALE NUMBER 9XQSCI 23 61K  
RUN NUMBER 616  
2018 KIA SORENTO  
VIN: JG-365820



KEYS



FRONT OF VEHICLE



FRONT BUMPER



ROOF



LIFTGATE



REAR BUMPER



LF TIRE



RF TIRE



LR TIRE



RR TIRE



RADIO



GLOVE COMPARTMENT



BACKUP CAMERA INOPERABLE



FRONT BUMPER MULTIPLE  
SCRATCHES & CHIPS



HOOD MULTIPLE SCRATCHES, DENTS  
& CHIPS WITH PAINT DAMAGE



ADDITIONAL PHOTOS FOR  
SALE NUMBER 9XQSCI 23 61K  
RUN NUMBER 616  
2018 KIA SORENTO  
VIN: JG-365820  
(Continued)



HOOD RELEASE HANDLE BROKEN



IGNITION MISSING===COVER ONLY



LEFT QUARTER PANEL MULTIPLE  
SCRATCHES



LF DOOR KEY CYLINDER DAMAGE



LF DOOR MULTIPLE SCRATCHES &  
CHIPS



LF WHEEL CURB RASH



LIFTGATE MULTIPLE SCRATCHES



LR DOOR GLASS TINT PEELING



LR DOOR MULTIPLE SCRATCHES



RADIO INOPERABLE



REAR BUMPER MULTIPLE SCRATCHES




RF DOOR GLASS TINT PEELING



ADDITIONAL PHOTOS FOR  
SALE NUMBER 9XQSCI 23 61K  
RUN NUMBER 616  
2018 KIA SORENTO  
VIN: JG-365820  
(Continued)



**RF DOOR MULTIPLE SCRATCHES**



**RF FENDER MULTIPLE SCRATCHES**



**RF MIRROR HOUSING SCUFFED**



**RIGHT QUARTER PANEL MULTIPLE  
SCRATCHES**



**ROOF MULTIPLE SCRATCHES & DENTS**



**RR DOOR GLASS MISSING**



**RR DOOR MULTIPLE SCRATCHES**



**RR WHEEL CURB RASH**



**SPARE TIRE MISSING**